



NOTES:

CONNECTORS:

CN2 : POWER SUPPLY & INPUT CONTROL (8)

CN3 : OUTPUT CONTROL & SENSE (8)

CN4/5 : FANS (3)

CN6 : THERMAL RESISTOR / TRANSFORMER (3)

CN7-9 : LOW AC FROM TRANSFORMER

*1 : ONLY L500 / L300

*2 : ONLY L1000

*5 : UB: 15V (SPEED 1)
21V (SPEED 2)
26V (SPEED 3)

AC VOLTAGE 50/60 HZ MEASURED VOLTMETER 2000 OHMS/V

DC VOLTAGE MEASURED WITH VOLTMETER 100kOHM/V

ALTERATIONS RESERVED!										
				Last modified: 09.05.1997 11:36:24		Lcontrol1 POWER SUPPLY TURN ON DELAY FAN CONTROL				
				Last plotted: 30.07.2002 09:59:58						
H	34/97	9.5.	RST		DATE	NAME	CIRCUIT DIAGRAM 348 615 L300/500/1000 P550/1050			
G	25/96	13.2.	JST							1/1
F	17/95	27.3.	JST	DSG'D		STADLER				
E	129/94	20.10.	JST	CHK'D						
D	103/94	14.9.	JST	APP'D						
C	76/94	16.6.	JST	DYNACORD			2-			
B	74/94	16.6.	JST							
A	37/94	2.5.	JST							
SYMB.	REVISION	DATE	NAME							